

**SHOULDN'T NEED REPLACING**

- 1 x 180 $\mu$ f 385WV
- 1 x 8.2 $\mu$ f 50V

**REPLACE**

- 1 x 270 $\mu$ f 10V
- 1 x 47 $\mu$ f 25V
- 1 x 56 $\mu$ f 25V
- 2 x 270 $\mu$ f 25V
- 3 x 1000 $\mu$ f 10V

1000 $\mu$ f  
10V

270 $\mu$ f  
10V

1000 $\mu$ f  
10V

56 $\mu$ f  
25V

270 $\mu$ f  
25V

1000 $\mu$ f  
10V

270 $\mu$ f  
25V

47 $\mu$ f  
25V